Tanks Data	3	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # 15294	Contact No	Contact Number				
Facility Name Marathon		Contact email				
Address 831 E Colfax Ave South Bend 46617		Date of Inspection $5/19/23$				
Operator on Duty Name						
operator on Buty Name		Name of the Person Conducting Inspection Josh				
	Operator Train					
Operator Training current	Yes	No	OperatorNotified	Yes	No	
	ration/Notifica	tion Form		0		
Is Registration current with correct owner, operator etc.	Yes	Oylo	OperatorNotified	()/es	Olo	
	Release Detecti	ion			0	
Release Detection Method	⊘ ATG	C EIM	SIR	OIC	Other	
Make and Model	Franklin	Franklin FS TS-550 evo				
Does it have paper?	Ves	No	OperatorNotified	Yes	Oylo	
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	No	
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	No	
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Yes	No	
	Spill Bucket	s	977			
Are Spill Buckets Clean and free from water, debris, product etc	? Yes	No	OperatorNotified	Ves	Oko	
Are the Spill Bucket in good condition and free of damage/crack	s (V)/es	No	OperatorNotified	es	X _o	
	Fill Ports	0		O	Oio	
Is Fill pipe cap tight and fill pipe free from any obstruction?	(V)/es	No	OperatorNotified	(Tes	Olo	
	Piping/STP Sur	mps				
Are Sumps Clean and free from water, debris, product etc?	Yes	OV	OperatorNotified	(V)(es	No	
Under Dis	penser Contair	ments (UDC)				
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	Yes	No	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS FOLLOWING PROPER PA	SPOSSED OFF ROCEDUE BY A	ACCORDING 4 CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS	
Operator on Duty Name	Signature			Date		
317-645-0215 tanksdata@gmail.com				www.tanksdata.com		