Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # 15294	Contact Number				
Facility Name Marathon	Contact email				
Address 831 E Colfax Ave South Bend	Date of Inspection 1/13/23				
Operator on Duty Name 46617	Name of the Person Conducting Inspection Name of the Person Conducting Inspection				
	erator Traini				
Operator Training current	Yes	No	OperatorNotified	Yes	Ovo
Registrat	tion/Notificat	ion Form		^	
Is Registration current with correct owner, operator etc.	Yes	Oyo	OperatorNotified	Ves	Oyo
	elease Detecti	on		_	_
Release Detection Method	√ ATG	CIM	SIR	OIC	Other
Make and Model	Franklin	FS TS	5-550 evo		_
Does it have paper?	Yes	O_{N_0}	OperatorNotified	Yes	Oto
Is it in Alarm mode?	Yes	ON ₀	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	Yes	\sim No	OperatorNotified	Yes	No
	Spill Buckets	s		0	
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified	(Nes	Olo
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	Zes .	\times
·	Fill Ports	O.	operatorriotineu	O ^{cs}	C.o
Is Fill pipe cap tight and fill pipe free from any obstruction?	(Ves	No	OperatorNotified	Oes	Olo
Pi	ping/STP Sur	mps	•	0.0	0.0
Are Sumps Clean and free from water, debris, product etc?	Yes	(V)/0	OperatorNotified	OVes	Olo
Under Dispe	nser Contain	ments (UDC		Q.c.	O.º
Are UDCs clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified	OYes	Ola
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF	ACCORDING 4 CERTIFIED	TO FYISTING DILLES	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tankso	ssdata@gmail.com			www.tanksdata.com	
				W W.tanks	20