		1
		*//

317-645-0215 tanksdata@gmail.com					www.tanksdata.com	
perator on Duty Name		Signature		Date		
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO	OSSED OFF A CEDUE BY A	CERTIFIED	TO EXISTING RULES . CONTRACTOR.	AND REQU	LATIONS	
Are UDCs clean and free from water, debris, product etc?	Yes	$\bigcirc$ $^{10}$	OperatorNotified	O'es	Olo	
	nser Contain	ments (UDC)				
Are Sumps Clean and free from water, debris, product etc?	Yes	<b>⊘</b> /o	OperatorNotified	Ores	No	
	ping/STP Sun	ıps				
Is Fill pipe cap tight and fill pipe free from any obstruction?	(V) Yes	No	OperatorNotified	Oes	Olo	
	Fill Ports	0	Printed	U.S.	Cro	
Are the Spill Bucket in good condition and free of damage/cracks	Ves	No	OperatorNotified	Yes es	No	
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(No	OperatorNotified	Oes	Ola	
	Spill Buckets		- perator rottled	Ocs	CNO	
Necessary Monthly Printout Taken	Yes	No	Operator Notified	Yes	No	
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	No	
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	No	
Does it have paper?	Yes	No	OperatorNotified	Yes	Olo	
Make and Model	Franklin		-550 evo	Orc	Tiller	
Release Detection Method	<b>(</b> √)ATG	<b>C</b> IM	GIR	OIC	Other	
	elease Detection		Operatornouned	Ves	CHO	
Is Registration current with correct owner, operator etc.	Yes	No No	OperatorNotified	0	0.	
	tion/Notificat	ONo	OperatorNotified	Yes	ONo	
Operator Training current	perator Train			0		
46617	Conducting	Inspection	Josh Ride	(		
Operator on Duty Name	Name of the Person					
address 831 E Colfax Ave South Bend	Date of Inspection		3/15/23			
acility Name Marathon	Contact email					
ST Facility I.D.( (FID) # 15294	Contact Number					
Tanks Data	30 DAYS WALK THROUGH INSPECTION					