Tanks Data	3	0 DAYS W	ALK THROUGH	INSPEC	CTION
ST Facility I.D.((FID) # 15294	Contact Number				
acility Name Marathon	Contact email				
address 831 E Colfax Ave South Bend 46617	Date of Inspection 10/13/6			2	
Operator on Duty Name	Name of the Person Conducting Inspection			Rider	
Or	erator Train		000,0		
Operator Training current	Yes	No	OperatorNotified	Yes	No
Registra	tion/Notificat	0	operatorrionnea	0.00	0.0
Is Registration current with correct owner, operator etc.	Yes	No	OperatorNotified	Ves	Olo
Re	elease Detecti	on			
Release Detection Method	(V)ATG	CIM	SIR	OIC	Other
Make and Model	FFS TS-550 evo			0	
Does it have paper?	Yes	No	OperatorNotified	Yes	Olo
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	Olo.
Interstitial Monitoring Sensor Status Normal	(V)Yes	No	OperatorNotified	Ves	No
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Yes	No
	Spill Buckets				
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	No	Operator Notified	(Zes	Olo
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	es	XI.
	Fill Ports	0		O.	0.0
Is Fill pipe cap tight and fill pipe free from any obstruction?	(Ves	No	OperatorNotified	Tes	Olo
Pi	ping/STP Sur	nps			
Are Sumps Clean and free from water, debris, product etc?	Yes	(V)Vo	OperatorNotified	(V)/es	No
Under Dispe	nser Contain	ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	(Ves	ONO
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF A	ACCORDING CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
perator on Duty Name		Signature		Date	
317-645-0215 tanks	nksdata@gmail.com			www.tanksdata.com	