

30 DAYS WALK THROUGH INSPECTION

Tanks Data		Contact Number
UST Facility I.D. (FID) # 15294		Contact email
Facility Name	McArthur	Date of Inspection
Address	831 E Colfax Ave, South	Name of the Person Conducting Inspection
Operator on Duty Name	Brenda W 46617	AKSHIT

Operator Training current	Registration/Notification Form	Release Detection	Operator Training	Operator Notified	Operator Notified
☐ Yes ☐ No	☐ Yes ☐ No	☒ ATG ☐ DIM ☐ SIR ☐ IC ☐ Other	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
Is Registration current with correct owner, operator etc.	Release Detection Method	Release Detection	Operator Training	Operator Notified	Operator Notified
Release Detection Method Make and Model Does it have paper? Is it in Alarm mode? Interstitial Monitoring Sensor Status Normal Necessary Monthly Printout Taken	FES-TS-6 VOS50	☒ Yes ☐ No	☒ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
Are Spill Buckets Clean and free from water, debris, product etc? Are the Spill Bucket in good condition and free of damage/cracks	Spill Buckets	☒ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
Is Fill pipe cap tight and fill pipe free from any obstruction? Are Sumps Clean and free from water, debris, product etc?	Fill Ports Piping/STP Sumps	☒ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
Are UDCs clean and free from water, debris, product etc? NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.	Under Dispenser Containments (UDC)	☒ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No

Operator on Duty Name	Signature	Date
317-645-0215	tanksdata@gmail.com	www.tanksdata.com