



5296 Breakers Way, Carmel, IN 46033

Date 2/12/25

LIQUID SENSOR FUNCTIONALITY TESTING

Facility Name:	Marathon
Address:	831 E Colfax Ave
City, State, Zip Code:	South Bend, IN 46617
Facility I.D. #:	15294

Owner:	RA Colfax Property LLC
Address:	4232 W Ridgeway Dr
City, State, Zip Code:	La Porte, IN, 46350
Phone #:	

This procedure is to determine whether liquid sensors located in the interstitial space of UST systems are able to detect the presence of water and fuel. See PEI/RP1200 Section 8.3 for the test procedure.

Sensor Location	STP 1	STP 2						
Product Stored	Regular	Premium						
Type of Sensor	Non-Discri	Non-Discri						
Test Liquid	Water	Water						
Is the ATG console clear of any active or recurring warnings or alarms regarding the leak sensor? If the sensor is in alarm and functioning, indicate why.	Yes	Yes						
Is the sensor alarm circuit operational?	Yes	Yes						
Has sensor been inspected and in good operating condition?	Yes	Yes						
When placed in the test liquid, does the sensor trigger an alarm?	Yes	Yes						
When an alarm is triggered, is the sensor properly identified on the ATG console?	Yes	Yes						
Any "No" answers indicates the sensor fails the test.								
Test Results	Pass	Pass						

Comment

Tester's Name : Josh Rider

Tester's Signature : Josh Rider