					•	
Tanks Data	3	30 DAYS WALK THROUGH			CTION	
UST Facility I.D.((FID) # 15672	Contact N	Contact Number				
Facility Name Phillips 66	Contact en	Contact email				
Address 203 N Main St North Liberty 4655	Date of Ins	Date of Inspection 6/6/23				
Operator on Duty Name	Name of the	Name of the Person Conducting Inspection Josh				
0	perator Train	ning		_	_	
Operator Training current	Yes	ON ₀	OperatorNotified	OYes .	O _N o	
	ation/Notifica			0	O:	
Is Registration current with correct owner, operator etc.	OYes	. ONo	OperatorNotified	Ves	Olo	
	Release Detect	_	Cin	∩IC	Other	
Release Detection Method	ATG	OIM O	OSIR .	Oic	Other	
Make and Model	VR	TLS-3	Operator Notified	Nes	Ora	
Does it have paper?	Yes	Q^{N_0}		\sim	X,0	
Is it in Alarm mode?	⊘ Yes	Q_{N_0}	OperatorNotified	Yes	\searrow	
Interstitial Monitoring Sensor Status Normal	O'es	\bigcirc No	OperatorNotified	Yes	No.	
Necessary Monthly Printout Taken	Yes	O_{N^0}	OperatorNotified	Yes	O _{No}	
	Spill Bucke			_	_	
Are Spill Buckets Clean and free from water, debris, product etc?		\bigcirc 10	OperatorNotified	O es	Q√o	
Are the Spill Bucket in good condition and free of damage/cracks	_	O _N o	OperatorNotified	Oes	Olo	
	Fill Ports	_		^	0.	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Ves (CTP)	O_{i0}	OperatorNotified	Oes	Olo	
	Piping/STP Su		On anoton Notified	(Ves	0.	
Are Sumps Clean and free from water, debris, product etc?	OYes Contain	nments (UDC)	OperatorNotified	Vres	O ₁₀	
•	_	No No		Ox.	0.	
Are UDCs clean and free from water, debris, product etc?	Yes	•	Operator Notified	Vies	O ₁₀	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS. FOLLOWING PROPER PR	OCEDUE BY	A CERTIFIED	CONTRACTOR.	AND REQU	LATIONS	
Operator on Duty Name		Signature		Date		
317-645-0215 tank	tanksdata@gmail.com			www.tanks	data.com	

•