Tanks Data	30 DAYS WALK THROUGH INSPECTION				
JST Facility I.D.((FID) # 1567a	Contact Number				
acility Name Phillips 66	Contact email				
Address 203 N Main St North Liberty 46554	Date of Inspection 8/25/23				
Operator on Duty Name				Rider	
0	perator Train	ing			
Operator Training current	Yes	O_{No}	OperatorNotified	Yes	O _N o
	tion/Notificat	tion Form		_	_
Is Registration current with correct owner, operator etc.	Yes	O√o	OperatorNotified	Ves	\bigcirc 10
	elease Detecti	_	O	O	<u> </u>
Release Detection Method	√ ATG	CIM	OSIR	Oic	Other
Make and Model	VR	TLS-35			
Does it have paper?	Yes	\bigcirc No	OperatorNotified	Yes	\bigcirc 10
Is it in Alarm mode?	Yes	\bigcirc No	OperatorNotified	OYes .	\bigcirc 10
Interstitial Monitoring Sensor Status Normal	Yes	O _{No}	OperatorNotified	O'res	Ovo
Necessary Monthly Printout Taken	Yes	\bigcirc No	OperatorNotified	O'es	O _V o
	Spill Bucket	is			•
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	\bigcirc No	OperatorNotified	(Ves	Olo
Are the Spill Bucket in good condition and free of damage/cracks	(V)/es	No	OperatorNotified	Ces	No
	Fill Ports	0		0	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	Olo	OperatorNotified	(Tes	Olo
	iping/STP Su	mps		_	
Are Sumps Clean and free from water, debris, product etc?	Yes	\bigcirc 10	OperatorNotified	(√)Yes	Olo
Under Disp	enser Contai	nments (UDC)		0
Are UDCs clean and free from water, debris, product etc?	Yes	\bigcirc No	OperatorNotified	(V) es	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS. FOLLOWING PROPER PR	POSSED OFF OCEDUE BY	ACCORDING A CERTIFIED	G TO EXISTING RULES CONTRACTOR.	S AND REQU	ILATIONS
ator on Duty Name		Signature	:	Date	
	ıksdata@gmail.com			www.tanksdata.com	