

000
Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) #	15672	Contact Number	
Facility Name	Pallings 6	Contact email	
Address	203 N Main St, North Liberty	Date of Inspection	12/23/21
Operator on Duty Name	IN 46554	Name of the Person Conducting Inspection	AKSHIT

	Operator Training	Registration/Notification Form	Release Detection	Operator Notified	Yes	No
Operator Training current	☐ Yes	☐ No	☐ Yes	☐ No	☐ Yes	☐ No
Is Registration current with correct owner, operator etc.	☐ Yes	☐ No	☐ Yes	☐ No	☐ Yes	☐ No
Release Detection Method	☒ ATG	☐ CIM	☐ BIR	☐ IC	☐ Other	
Make and Model	VR TUS 350					
Does it have paper?	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No	
Is it in Alarm mode?	☐ Yes	☒ No	Operator Notified	☐ Yes	☐ No	
Interstitial Monitoring Sensor Status Normal	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No	
Necessary Monthly Printout Taken	☐ Yes	☐ No	Operator Notified	☐ Yes	☐ No	
Spill Buckets	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No	
Are Spill Buckets Clean and free from water, debris, product etc?	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No	
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No	
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No	
Are Sumps Clean and free from water, debris, product etc?	☐ Yes	☒ No	Operator Notified	☒ Yes	☐ No	
Under Dispenser Containments (UDC)	☐ Yes	☒ No	Operator Notified	☐ Yes	☐ No	
Are UDCs clean and free from water, debris, product etc?	☐ Yes	☒ No	Operator Notified	☐ Yes	☐ No	

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name _____ Signature _____ Date _____

317-645-0215 tanksdata@gmail.com www.tanksdata.com