ATG Roon bocked

Tanks Data	3	0 DAYS W	VALK THROUGH	IINSPE	CTION
UST Facility I.D.((FID) # 15677	Contact Number				
Facility Name Phillips 6	Contact email				
Address 20 3N May St	Date of Inspection $07-10-7075$				
Operator on Duty Name	Name of the Person Conducting Inspection Current				
Op	erator Train				
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONO
	tion/Notifica				
Is Registration current with correct owner, operator etc.	Yes	. ON₀	OperatorNotified	Ves	Olo
	lease Detect			_	
Release Detection Method	ATG	CIM	SIR	OIC	Other
Make and Model					
Does it have paper?	Yes	O <sub>No</sub>	OperatorNotified	Yes .	$\bigcirc$ 10
Is it in Alarm mode?	Yes	ON <sub>0</sub>	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	ONo.	OperatorNotified	Yes	Oyo
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	() res	ONO.
	Spill Bucket	s		~	
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	( No	OperatorNotified	Oes	ONO
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	No
	Fill Ports	$\circ$			
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	(No	OperatorNotified	Oes	Olo
Pip	ing/STP Sur	mps		_	
Are Sumps Clean and free from water, debris, product etc?	OYes .	(D)/o	OperatorNotified	(Qres	Olo
Under Disper	nser Contain	ments (UDC)		7	
Are UDCs clean and free from water, debris, product etc?	OYes .	(ONO	OperatorNotified	Tes	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO	OSSED OFF	ACCORDING CERTIFIED	TO EXISTING RULES		
Operator on Duty Name		Signature	$\supset$	Date >	7-60-70
317-645-0215 tanksd	ata@gmail.c	om/_		www.tanks	data com
turinsu	Co Billair.			THE TELES	2022051