

TRIENNIAL INSPECTION

Facility Name: LUCKY MART

Test Date: 04/03/2025

Facility Address: 203 N MAIN STREET NORTH LIBERTY IN ...

Facility ID: 15672

SPILL CONTAINER INTEGRITY TESTING

Product	RUL							
Test Type	Repair							
Clean of liquid/debris	YES							
VISUAL INSPECTION	PASS							
Test Start Time	2:15							
Test End Time	3:15							
Starting Water Level (inches)	10							
Ending Water Level (inches)	10							
Water Level Change (inches)	0							
HYDROSTATIC TEST RESULT	PASS							
Double wall	NO							
Vacuum Test Length (minutes)								
Starting Inches of Water								
Ending Inches of Water								
VACUUM TEST RESULT								

Comments

Replaced bad drain for T2 RUL spill bucket. Tested good.

Technician Name: Jack Davids

Dispatch # 413678

B&K Equipment completes testing and inspections per recommended practices of PEI RP1200-19