

30 DAYS WALK THROUGH INSPECTION

Tanks Data		Contact Number
UST Facility I.D. (FID) #	15672	Contact email
Facility Name	Pipeline 66	Date of Inspection
Address	203 N Mainst, North	Name of the Person Conducting Inspection
Operator on Duty Name	Liberty 46554	AKSMT
Operator Training current	☐ Yes ☐ No	Operator Notified ☐ Yes ☐ No
Registration current with correct owner, operator etc.	☐ Yes ☐ No	Operator Notified ☐ Yes ☐ No
Release Detection Method	☒ ATG ☐ CIM ☐ SIR	Operator Notified ☐ Yes ☐ No
Make and Model	VA-TLS 350	Operator Notified ☐ Yes ☐ No
Does it have paper?	☒ Yes ☐ No	Operator Notified ☐ Yes ☐ No
Is it in Alarm mode?	☒ Yes ☐ No	Operator Notified ☐ Yes ☐ No
Interstitial Monitoring Sensor Status Normal	☒ Yes ☐ No	Operator Notified ☐ Yes ☐ No
Necessary Monthly Printout Taken	☒ Yes ☐ No	Operator Notified ☐ Yes ☐ No
Are Spill Buckets Clean and free from water, debris, product etc?	☒ Yes ☐ No	Operator Notified ☐ Yes ☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes ☐ No	Operator Notified ☐ Yes ☐ No
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes ☐ No	Operator Notified ☐ Yes ☐ No
Are Sumps Clean and free from water, debris, product etc?	☒ Yes ☐ No	Operator Notified ☐ Yes ☐ No
Under Dispenser Containments (UDC)	☒ Yes ☐ No	Operator Notified ☐ Yes ☐ No
Are UDCs clean and free from water, debris, product etc?	☒ Yes ☐ No	Operator Notified ☐ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name _____ Signature _____ Date _____

317-645-0215 tanksdata@gmail.com www.tanksdata.com 20220516