

Petroleum Testing Services

PO BOX 146
Yorktown, IN 47396
(765) 749-5540

Email: petroleumtesting@aol.com

DATE: 9-3-2021	TIME: 9:00A
SITE ADDRESS Southside Shell 1401 E 29 th St Muncie, In 47302	

AUTOMATIC TANK GAUGE INSPECTION				
MAKE /MODEL OF ATG : VR 350				
TANK	1	2	3	4
PRODUCT	UNL1	UNL2	PREM	A DSL
TANK VOLUME / GALLONS	6016	6016	6016	5264
TANK DIAMETER	96	96	96	96
MANUAL STICK READING				
ATG LEVEL	57.46	57.78	42.31	45.24
TANK PROBE REMOVED AND INSPECTED?	YES	YES	YES	YES
TANK PROBE HAS DAMAGED OR MISSING PARTS?	NO	NO	NO	NO
TANK PROBE DAMAGED OR MISSING PARTS REPLACED?	NA	NA	NA	NA
FLOATS MOVE FREELY ON STEM?	YES	YES	YES	YES
DOES THE FUEL FLOAT AGREE WITH CONSOLE?	YES	YES	YES	YES
DOES WATER FLOAT AGREE WITH CONSOLE?	YES	YES	YES	YES
WATER FLOAT ALARM ACTIVATION CORRESPONDS WITH CONSOLE?	YES	YES	YES	YES
OVERFILL ALARM ACTIVATION CORRESPONDS WITH CONSOLE?	YES	YES	YES	YES
ALARMS ARE CLEARED?	YES	YES	YES	YES
RESULT	PASS	PASS	PASS	PASS
STP SUMP SENSORS ACTIVATES ALARM	NA	NA	NA	NA

INSPECTED BY: JOHN LANNOM

UC20129333

Petroleum Testing Services

PO BOX 146
Yorktown, IN 47396
(765) 749-5540

Email: petroleumtesting@aol.com

DATE: 9-3-2021	TIME: 9:00A
SITE ADDRESS Southside Shell 1401 E 29 th St Muncie, In 47302	

AUTOMATIC TANK GAUGE INSPECTION

MAKE /MODEL OF ATG : VR 350				
TANK	5			
PRODUCT	T DSL			
TANK VOLUME / GALLONS	12032			
TANK DIAMETER	96			
MANUAL STICK READING	30			
ATG LEVEL	30.18			
TANK PROBE REMOVED AND INSPECTED?	YES			
TANK PROBE HAS DAMAGED OR MISSING PARTS?	NO			
TANK PROBE DAMAGED OR MISSING PARTS REPLACED?	NA			
FLOATS MOVE FREELY ON STEM?	YES			
DOES THE FUEL FLOAT AGREE WITH CONSOLE?	YES			
DOES WATER FLOAT AGREE WITH CONSOLE?	YES			
WATER FLOAT ALARM ACTIVATION CORRESPONDS WITH CONSOLE?	YES			
OVERFILL ALARM ACTIVATION CORRESPONDS WITH CONSOLE?	YES			
ALARMS ARE CLEARED?	YES			
RESULT	PASS			
STP SUMP SENSORS ACTIVATES ALARM	NA			

INSPECTED BY: JOHN LANNOM

UC20129333