

Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) # 2255		Contact Number			
Facility Name Shell		Contact email			
Address 1401 E 24th St		Date of Inspection 2-29-24			
Operator on Duty Name		Name of the Person Conducting Inspection Austin B.			
Operator Training		Operator Training			
Operator Training current		☐ Yes ☐ No	Operator Notified	☐ Yes ☐ No	
Is Registration current with correct owner, operator etc.		Registration/Notification Form	☐ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Release Detection Method		Release Detection	☒ ATG ☐ CIM	☐ SIR	☐ IC ☐ Other
Make and Model		Gilbarco EMC			
Does it have paper?		☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No	☐ Yes ☐ No
Is it in Alarm mode?		☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No	☐ Yes ☐ No
Interstitial Monitoring Sensor Status Normal		☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No	☐ Yes ☐ No
Necessary Monthly Printout Taken		☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No	☐ Yes ☐ No
Are Spill Buckets Clean and free from water, debris, product etc?		Spill Buckets	☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Are the Spill Bucket in good condition and free of damage/cracks		☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No	☐ Yes ☐ No
Is Fill pipe cap tight and fill pipe free from any obstruction?		Fill Ports	☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Are Sumps Clean and free from water, debris, product etc?		Pipeline/STP Sumps	☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Are UDCs clean and free from water, debris, product etc?		Under Dispenser Containments (UDC)	☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name
317-645-0215
Signature
Date
tanksdata@gmail.com
www.tanksdata.com