

Overfill Equipment Inspection

Facility Name: SHELL HOOSIER PETE		Facility Number: 2255		
Facility Address: 1401 E 29TH STREET		Inspection Date: 11/14/2022		
Facility City: MUNCIE		Qualified Person: TERRY D BUSSELL		
Facility Zip Code: 47302		Certification Number: UC1999OH649667C		
Tank Number	1	2	3	4
Capacity	6016	6016	6016	5264
Product stored	REG UNLEADED	REG UNLEADED	PREM UNLEADED	DIESEL CAR
Overfill equipment manufacturer	VEEDER ROOT	VEEDER ROOT	VEEDER ROOT	VEEDER ROOT
Type (Check all that apply)	☐ Shutoff device	☐ Shutoff device	☐ Shutoff device	☐ Shutoff device
	☐ Ball float valve	☐ Ball float valve	☐ Ball float valve	☐ Ball float valve
	☒ Overfill alarm	☒ Overfill alarm	☒ Overfill alarm	☒ Overfill alarm
Automatic Shutoff Device Inspection				
Drop tube removed from tank?	Yes / No	Yes / No	Yes / No	Yes / No
Drop tube and float mechanisms are free of debris?	Yes / No	Yes / No	Yes / No	Yes / No
Float moves freely without binding and poppet moves into flow path?	Yes / No	Yes / No	Yes / No	Yes / No
Bypass valve in drop tube (if present) is open and free of blockage?	Yes / No	Yes / No	Yes / No	Yes / No
Flapper is adjusted to shut off at 95% capacity?	Yes / No	Yes / No	Yes / No	Yes / No
Overfill Alarm Inspection				
Electronic device and probe are operating properly?	(Yes) / No	(Yes) / No	(Yes) / No	(Yes) / No
Alarm activates at 90% capacity or within one minute of overfill?	(Yes) / No	(Yes) / No	(Yes) / No	(Yes) / No
Alarm can be heard and/or seen from where the tank is fueled?	(Yes) / No	(Yes) / No	(Yes) / No	(Yes) / No
Ball Float Valve Inspection				
Tank top fittings are vapor-tight and leak-free?	Yes / No	Yes / No	Yes / No	Yes / No
Ball float cage free of debris?	Yes / No	Yes / No	Yes / No	Yes / No
Ball is free of holes, cracks and moves freely in cage?	Yes / No	Yes / No	Yes / No	Yes / No
Vent hole in pipe is open and near top of tank?	Yes / No	Yes / No	Yes / No	Yes / No
Ball float pipe is proper length to restrict flow at 90% capacity?	Yes / No	Yes / No	Yes / No	Yes / No
Inspection Results (Circle One)	(Pass) / Fail	(Pass) / Fail	(Pass) / Fail	(Pass) / Fail
INSTALLED OVERFILL PREVENTION ALARM				

Keep this record for three years

Overfill Equipment Inspection

Facility Name: SHELL HOOSIER PETE		Facility Number: 2255		
Facility Address: 1401 E 29TH STREET		Inspection Date: 11/14/2022		
Facility City: MUNCIE		Qualified Person: TERRY D BUSSELL		
Facility Zip Code: 47302		Certification Number: UC1999OH649667C		
Tank Number	5			
Capacity	12032			
Product stored	DIESEL TRUCK			
Overfill equipment manufacturer	VEEDER ROOT	VEEDER ROOT	VEEDER ROOT	VEEDER ROOT
Type (Check all that apply)	☐ Shutoff device	☐ Shutoff device	☐ Shutoff device	☐ Shutoff device
	☐ Ball float valve	☐ Ball float valve	☐ Ball float valve	☐ Ball float valve
	☒ Overfill alarm	☐ Overfill alarm	☐ Overfill alarm	☐ Overfill alarm
Automatic Shutoff Device Inspection				
Drop tube removed from tank?	Yes / No	Yes / No	Yes / No	Yes / No
Drop tube and float mechanisms are free of debris?	Yes / No	Yes / No	Yes / No	Yes / No
Float moves freely without binding and poppet moves into flow path?	Yes / No	Yes / No	Yes / No	Yes / No
Bypass valve in drop tube (if present) is open and free of blockage?	Yes / No	Yes / No	Yes / No	Yes / No
Flapper is adjusted to shut off at 95% capacity?	Yes / No	Yes / No	Yes / No	Yes / No
Overfill Alarm Inspection				
Electronic device and probe are operating properly?	<u>Yes</u> / No	Yes / No	Yes / No	Yes / No
Alarm activates at 90% capacity or within one minute of overfill?	<u>Yes</u> / No	Yes / No	Yes / No	Yes / No
Alarm can be heard and/or seen from where the tank is fueled?	<u>Yes</u> / No	Yes / No	Yes / No	Yes / No
Ball Float Valve Inspection				
Tank top fittings are vapor-tight and leak-free?	Yes / No	Yes / No	Yes / No	Yes / No
Ball float cage free of debris?	Yes / No	Yes / No	Yes / No	Yes / No
Ball is free of holes, cracks and moves freely in cage?	Yes / No	Yes / No	Yes / No	Yes / No
Vent hole in pipe is open and near top of tank?	Yes / No	Yes / No	Yes / No	Yes / No
Ball float pipe is proper length to restrict flow at 90% capacity?	Yes / No	Yes / No	Yes / No	Yes / No
Inspection Results (Circle One)	<u>Pass</u> / Fail	Pass / Fail	Pass / Fail	Pass / Fail
INSTALLED OVERFILL PREVENTION ALARM				

Keep this record for three years