

Facility # \_\_\_\_\_

Permit# \_\_\_\_\_

**TANK LINING/INTERNAL INSPECTION/REPAIR COMPLIANCE REPORT****FACILITY** - Facility ID # \_\_\_\_\_

(Name and address where tanks are located:)

Hoosier Pete

Name  
1401 E. 29th St.Street Address  
Muncie, INCity State Zip County  
TJ

Contact Person

Phone

**CONTRACTOR:**

WILLIAMS, BECK AND HESS INC.

Company Name  
P.O. BOX 46Street Address  
WEST NEWTON, IN. 46183City State Zip  
WILLIAM J. HARRISON 317-856-5659Contact Person Phone  
UC2018IN12869 07/17/2022

Contractor License #

Expiration Date

| Compliance Item                                         | Tank #1     | Tank #2 | Tank #3 | Tank #4 |
|---------------------------------------------------------|-------------|---------|---------|---------|
| Tank approved for Lining (Y/N)                          | N/A         |         |         |         |
| Full White Metal Blast 3 to 4 mils Min. (see figure 5)  | N/A         |         |         |         |
| Mil Profile (Y/N)                                       | N/A         |         |         |         |
| Reinforcing Plates Installed (#)                        | N/A         |         |         |         |
| Entire Inside Surface Coated Evenly (Y/N)               | YES         |         |         |         |
| Number of Coating Thickness Readings                    | 42          |         |         |         |
| Max. Coating Thickness Reading Top, Side, Bottom (mils) | 101 107 112 |         |         |         |
| Number of Hardness Readings                             | 25          |         |         |         |
| Max. Hardness Reading                                   | 84          |         |         |         |
| Min. Hardness Reading                                   | 83          |         |         |         |
| Full Holiday Test Passed (Y/N)                          | YES         |         |         |         |
| Sketch of Tanks on Reverse (Y/N)                        | NO          |         |         |         |
| Number of Holes                                         | NONE        |         |         |         |
| Age of Tank                                             | UNKNOWN     |         |         |         |
| Seam Leak                                               | NO          |         |         |         |

Brand &amp; Model of Thickness Tester

ELCOMETER 345

Brand &amp; Model of Hardness Tester

BARBER COLMAN GYZJ935

Brand &amp; Number of Lining Material

ARMOR SHEILD/ IECC 125

Brand &amp; Model of Holiday Tester

ELECTRO-TECHNIC PRODUCTS BD-50E

Brand &amp; Model of Ultrasonic Thickness Gauge

KRAUTKRAMER DMS2

**OATH:**

I certify that the above information is correct and that the subject tank lining work was completed according to specifications of the lining material manufacturer and NLPA 631.

Signature of Authorized Field Installer



Company WILLIAMS, BECK AND HESS INC.

Date 07/23/2021

# REINSPECTION REPORT

Date

7/20/21

We completed reinspection of your tanks recently and wish to submit a report on the condition of the tank(s) for your record and information

Station ☒

Bulk Plant ☐

Location

Hoosier Lake 1401 E. 29th St. Muncie, IN

Date

7/20/21

Number of Tanks

1 - 12m Round

Condition of lining

Lining looked good and met ~~the~~ testing

Repairs on tank lining

requirements.

No Repairs

Remarks relative to internal or external corrosion for all tanks

Tank met LAT  
scan criteria and passed 5 year  
inspection.

WILLIAMS, BECK & HESS, INC.

5 YEAR

10 YEAR

15 YEAR

20 YEAR

25 YEAR

By

William Hess