

5296 Breakers Way, Carmel, IN 46033

	www.tanksdata.com
×	tanksdata@gmail.com
	(317)-300-6065

Date

03.04.2024

UST Annual Walkthrough Inspection

1. UST Facility Information												
Facility I.D. #:	2255											
UST Facility Name	Shell											
UST Facility Physical Address	Street Address :	1401 E 29 St	City:	Muncie	Zip Code :	IN 47302						

2. Annual Inspection Checklist

Category	Description		Description		N/A	'A Tank1		Tank 2		Tank 3			Tank4		Tank 5		Tank 6		Tank 7		8
	Cap in good condition, seals tightly, hole sealed where				1				Yes ▼		↓	Yes			—				—		
	probe wire goes through			Yes		Yes		163	<u> </u>	Yes		162	Ľ	•					Ĺ		
ATG Manhole	Junction box has cover, not corrod wiring in good condition	ea; intrinsically safe		No	•	Yes		Yes	V	Yes	•	Yes	_		_		•		•		
	Manhole cover in good condition			Yes	•	Yes	•	Yes	•	Yes	•	Yes	•		•	•	•		•		
	Functionality Test Date :	3/4/24		-	•	-	•		•		•		•	-	•		•		•		
	Single-walled spill containment manhole tightness tested within last 3 years			Yes	•	Yes	•	Yes	•	Yes	•	Yes	_	-	•		•		•		
	Double-walled spill containment manhole tightness tested within last 3 years OR inspected monthly			•	•	-	•		•		•		•		•		•		•		
Spill Bucket	Are spill buckets free of product, water and debris?			No	•	No	•	No	•	No	•	No	▼		•	. [•		~		
	Are spill buckets free of damage/cracks?			No	•	Yes	•	Yes	•	No	•	No	•		•]. [•		•		
	HSB Test Date :	3/4/24			•		•		•		•		•		•		•		•		
	Drop tube shutoff valve passes inspection & excessive corrosion not present			-	•		•		•		•		•		•	-	•		•		
Overfill	Ball float valve passes inspection, can be removed & excessive corrosion not present			•	•	-	•		•	-	•		•	-	•		•		•		
Prevention	Overfill alarm passes inspection			Yes	•	Yes	•	Yes	•	No	•	No	lacksquare		•		•		~		
	OPV Test Date :	3/4/24		-	•	-	•		•		•		•		•		•		•		
	Galvanic Cathodic Protection test has been conducted within the past 3 years and the test passed		v	•	•		•		•		•		•		<u> </u>	-	•		•		
Corrosion	Impressed Current Cathodic Protection test has been conducted within the past 3 years and the test passed		~		•		•		•		•		•		•	-	•		•		
Protection	Tank Lining inspected as required and in good condition				•		•		•		•		T		•		•		•		
	CP Test Date :		V	-	•	-	•		•		•		•		•		•		•		

Category	Description		N/A	/A Tank1		Tank 2 Unl 2		Tank 3		Tank4		Tank 5		Tank 6	Tank 7	Tai	Tank 8	
	12 Months of RD printed and on site			No	-	No	▼	No	┰	No	▼	No			<u> </u>	<u>-</u>	—	
	Release Detection Report have issues	in past months		No	~	No	▼	No	•	No	•	No			. [<u>-</u>].	lacksquare	
Release Detection	ATG console has any history of alarm	in past months		No	V	No	▼	No	▼	No	-	No	_		ļ. <u>[</u>	<u>-</u>		
	Release Detection Type :				•		•		-		•	-		. •]. [•	
	Liquid and debris removed from sump	?			T		•		▼		T					<u>-</u>		
Containment Sumps	Are containment sumps free of damag	ge/cracks?			•		•		•		•	•			. [-	
	HSC Test Date :				•		•	•	•		•	•	•		<u> </u>		•	
Stage I Testing	Verify that Stage I testing has been co results are passing	enducted and test			•		•		•		•	-	▼]. [-	•	
Name (Class A & B	Operator) :																	
Name (Person cond	lucted the inspection):						A	Austin	Fis	sher								
Signature (Person o	gnature (Person conducted the inspection): Austin Fisher																	