	30	DAYS W	ALK THROUGH	INSPEC	TION	
Tanks Data						
UST Facility I.D.((FID) # 2247	Contact Number					
Facility Name 600000		Contact email Date of Inspection 07-02-7075				
Address 2005 le Memorial Des 47302	Date of Insp	ection O	7-06-10	23		
Operator on Duty Name	Name of the Person Conducting Inspection		Guypreet			
Op	erator Traini	ng		<u> </u>		
Operator Training current	Yes	ONo	OperatorNotified	OYes	Oio	
Registrat	ion/Notificati	on Form	O Wastflad	Over	Olo	
is Registration current with control of	OYes	ON0	OperatorNotified	U ₁₀₀		
Re	elease Detection		()BIR	OIC	Other	
Release Detection Method	(9ATG	CIM	O III	O.		
Make and Model VR7L5-33	0	0	OperatorNotified	Oves	Oko.	
Does it have paper?	Yes	ZNº	[4] [4] [4] [4] [4] [4] [4] [4] [4] [4]	X	\times	
Is it in Alarm mode?	OYes	QNo	OperatorNotified	X.	\times	
Interstitial Monitoring Sensor Status Normal	Ores	O _{No}	OperatorNotified	Xres	X.°	
Necessary Monthly Printout Taken	Yes	ONO	OperatorNotified	Oes	O_{0}	
	Spill Buckets					
Are Spill Buckets Clean and free from water, debris, product etc?	Ores	(910	OperatorNotified	(9es	Q¥0	
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	ONO	OperatorNotified	Oes	O10	
	Fill Ports			_		
Is Fill pipe cap tight and fill pipe free from any obstruction?	O'es	Ovo	OperatorNotified	Oes	Olo	
Pi	ping/STP Sur	nps		0		
Are Sumps Clean and free from water, debris, product etc?	OYes .	(A)O	OperatorNotified	Ves	\bigcirc	
Under Dispe	enser Contain					
Are UDCs clean and free from water, debris, product etc?	OYes .	(1)No	OperatorNotified		Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OCEDUE BY A	ACCORDING CERTIFIED	TO EXISTING RULES CONTRACTOR.	S AND REQU	JLATIONS 2 2 2 2	
Operator on Duty Name		Signature		Date O	7-02-203	
	data@gmail.c	om Luy	evel /	www.tank		