

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

SEP 9. 2024 4:40 PM

CSLD TEST RESULTS

SEP 9. 2024 4:40 PM

T 1:REGULAR
PROBE SERIAL NUM 517863

0.2 GAL/HR TEST
PER: SEP 9. 2024 PASS

T 2:PREMIUM
PROBE SERIAL NUM 517864

0.2 GAL/HR TEST
PER: SEP 9. 2024 PASS

T 3:DIESEL
PROBE SERIAL NUM 636334

0.2 GAL/HR TEST
PER: SEP 9. 2024 PASS

T 4:KEROSENE
PROBE SERIAL NUM 212514

0.2 GAL/HR TEST
PER: SEP 9. 2024 PASS

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

SEP 9. 2024 4:40 PM

LIQUID STATUS

SEP 9. 2024 4:40 PM

L 1:NL SUMP
SENSOR NORMAL

L 2:PREM SUMP
SENSOR NORMAL

L 3:DIESEL SUMP
SENSOR NORMAL

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

SEP 9, 2024 4:40 PM

LEAK TEST REPORT

T 1:REGULAR
PROBE SERIAL NUM 517863

NO TEST DATA AVAILABLE

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

SEP 9, 2024 4:40 PM

LEAK TEST REPORT

T 2:PREMIUM
PROBE SERIAL NUM 517864

NO TEST DATA AVAILABLE

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

SEP 9, 2024 4:40 PM

LEAK TEST REPORT

T 3:DIESEL
PROBE SERIAL NUM 636334

NO TEST DATA AVAILABLE

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

SEP 9, 2024 4:40 PM

LEAK TEST REPORT

T 4:KEROSENE
PROBE SERIAL NUM 212514

NO TEST DATA AVAILABLE