

5296 Breakers Way, Carmel, IN 46033

	www.tanksdata.com
\boxtimes	tanksdata@gmail.com
9	(317)-300-6065

Date

7/24/24

UST Annual Walkthrough Inspection

1. UST Facility Information											
Facility I.D. #:	2259										
UST Facility Name	Hoyt Shell										
UST Facility Physical Address	Street Address :	2535 S Hoyt Ave	City:	Muncie	Zip Code :	47302					

2. Annual Inspection Checklist

Category	Description		N/A	/A Tank1		Tank 2		Tank 3			Tank4 Kero		Tank 5		Tank 6		,	Tank 8	
	Cap in good condition, seals tightly probe wire goes through	y, hole sealed where		Yes	-	Yes	~	Yes	~	Yes	~		~		▼		▼		
ATG Manhole	Junction box has cover, not corrod wiring in good condition	led; intrinsically safe		Yes	-	Yes	~	Yes	•	Yes	~		-		▼		-		,
	Manhole cover in good condition			Yes	▼	Yes	V	Yes	•	Yes	V		V		▼		=		-
	Functionality Test Date :	7/24/24			•		•		•	ē	•		V		-		-		
	Single-walled spill containment m tested within last 3 years	anhole tightness		Yes	•	Yes	-	Yes	-	Yes	-		¥		T		▼		-
	Double-walled spill containment n tested within last 3 years OR inspe				•		V		•		V		V	-	V		V		
Spill Bucket	Are spill buckets free of product, w	ater and debris ?		Yes	•	Yes	•	Yes	•	Yes	•		V		▼		▼		-
	Are spill buckets free of damage/c	racks?		No	•	Yes	•	Yes	•	Yes	•		•		•		•	. [
	HSB Test Date :	7/24/24			•		•		•		•		•		•		•		,
	Drop tube shutoff valve passes ins corrosion not present	pection & excessive		No	•	No	•	No	•		•		•		▼		•]
Overfill	Ball float valve passes inspection, excessive corrosion not present	can be removed &		-	•	-	•		•	No	•		-		~		~		
Prevention	Overfill alarm passes inspection				•		•		•		•		T		▼		V		-
	OPV Test Date :	7/24/24			•		•		•		•		•		▼		-		,
Corrosion Protection	Galvanic Cathodic Protection test within the past 3 years and the tes				•		•		•		•		•		V		T		,
	Impressed Current Cathodic Prote conducted within the past 3 years		~		•		•		•		•		•		V		▼		,
	Tank Lining inspected as required	and in good condition			•	-	•		•		•		T		V		$\overline{}$		•
	CP Test Date :		~	-	•		•		•		•		•		-		•		,

Category	Description		Tank 1		Tank 2		Tank 3		Tani	(4	Tank 5	Tank 6	Tank 7	Tank 8	
			Reg		Prem		Dies		Kero						
	12 Months of RD printed and on site		No	•	No	•	No	•	No	•					
	Release Detection Report have issues in past months		No	•	No	•	No	•	No	•					
Release Detection	ATG console has any history of alarm in past months		No	•	No	▼	No	•	Yes				. 🔽		
	Release Detection Type: ATG			•		_		•	•						
	Liquid and debris removed from sump?		Yes	lacksquare	Yes	_	Yes	<u> </u>							
Containment Sumps	Are containment sumps free of damage/cracks?		Yes	V	Yes	_	Yes	-							
	HSC Test Date :		•	•	•	•	•	•	•	•					
Stage I Testing	Verify that Stage I testing has been conducted and test results are passing	V	-	•		•		•	-	•					
Comments/I	Deficiencies:														
Name (Class A & B	Operator):														
Name (Person conducted the inspection):							Josh	Ric	der						
Signature (Person o	\ \														