

000
Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) #	2259	Contact Number	
Facility Name	Shell	Contact email	
Address	2535 Steptoe Ave, Murk,	Date of Inspection	05-05-25
Operator on Duty Name	gn-47302	Name of the Person Conducting Inspection	Nehru Singh

Operator Training ☐ Yes ☐ No Operator Notified ☐ Yes ☐ No

Registration current with correct owner, operator etc. ☐ Yes ☐ No Operator Notified ☐ Yes ☐ No

Release Detection Method ☒ ATG ☐ CIM ☐ SIR ☐ IC ☐ Other

Make and Model VR-TLS350

Does it have paper? ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Is it in Alarm mode? ☐ Yes ☒ No Operator Notified ☐ Yes ☐ No

Interstitial Monitoring Sensor Status Normal Operator Notified ☐ Yes ☐ No

Necessary Monthly Printout Taken Operator Notified ☐ Yes ☐ No

Spill Buckets Operator Notified ☐ Yes ☐ No

Are Spill Buckets Clean and free from water, debris, product etc? ☐ Yes ☒ No Operator Notified ☐ Yes ☐ No

Are the Spill Bucket in good condition and free of damage/cracks ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Fill Ports Operator Notified ☐ Yes ☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction? ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Piping/STP Sumps Operator Notified ☐ Yes ☐ No

Are Sumps Clean and free from water, debris, product etc? ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Under Dispenser Containments (UDC) Operator Notified ☐ Yes ☐ No

Are UDCs clean and free from water, debris, product etc? ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS

FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com