

8BUCKETS
HAVING
WATER

Tanks Data		30 DAYS WALK THROUGH INSPECTION	
UST Facility I.D. (PID) #	2259	Contact Number	
Facility Name	Shel	Contact email	
Address	25355 Hwy 4 Ave, Nencie	Date of Inspection	0212025
Operator on Duty Name	1247302	Name of the Person Conducting Inspection	AKSHIT
Operator Training current		Operator Training	
☐ Yes ☐ No		☐ Yes ☐ No	
Is Registration current with correct owner, operator etc.		Registration/Notification Form	
☐ Yes ☐ No		☐ Yes ☐ No	
Release Detection Method		Release Detection	
Make and Model		☒ ATG ☐ TIM ☐ BIR ☐ IC ☐ Other	
Does it have paper?		VR TUS 350	
☐ Yes ☐ No		☐ Yes ☐ No	
Is it in Alarm mode?		☐ Yes ☐ No	
☐ Yes ☐ No		☐ Yes ☐ No	
Interstitial Monitoring Sensor Status Normal		Operator/Notified	
Necessary Monthly Printout Taken		☐ Yes ☐ No	
☐ Yes ☐ No		☐ Yes ☐ No	
Are Spill Buckets Clean and free from water, debris, product etc?		Spill Buckets	
☐ Yes ☐ No		☐ Yes ☐ No	
Are the Spill Bucket in good condition and free of damage/cracks		☐ Yes ☐ No	
☐ Yes ☐ No		☐ Yes ☐ No	
Is Fill pipe cap tight and fill pipe free from any obstruction?		Fill Ports	
☐ Yes ☐ No		☐ Yes ☐ No	
Are Sumps Clean and free from water, debris, product etc?		Pipe/STP Sumps	
☐ Yes ☐ No		☐ Yes ☐ No	
Are UDCs clean and free from water, debris, product etc?		Under Dispenser Containments (UDC)	
☐ Yes ☐ No		☐ Yes ☐ No	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.		Operator/Notified	
☐ Yes ☐ No		☐ Yes ☐ No	
Operator on Duty Name		Signature	
317-645-0215		Date	
tanksdata@gmail.com		www.tanksdata.com	