	30 DAYS WALK THROUGH INSPECTION					
Tanks Data						
ST Facility I.D.((FID) # 2259	Contact Number					
acility Name Shell	Contact email					
1ddress 25355 Hout ANR 47302	Date of Inspection $0/-69-2025$					
Operator on Duty Name	Name of the Conducting I	Person Inspection	suproet			
Op	erator Trainin		7			
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONo	
가는 사람들이 되었다면 하는데 사람들이 되었다면 하는데 사람들이 되었다면 하는데	tion/Notification	on Form				
Is Registration current with correct owner, operator etc.	Yes	ON0	OperatorNotified	Ves	010	
	elease Detectio	CA	<u> </u>	<u></u>		
Release Detection Method	ATG	<b>DIM</b>	SIR	Oic	Other	
Make and Model	KILS-	550				
Does it have paper?	<b>O</b> Yes	QN <sub>0</sub>	OperatorNotified	Yes	QVo	
Is it in Alarm mode?	Yes	O <sub>N</sub> o	OperatorNotified	Yes	Olo	
Interstitial Monitoring Sensor Status Normal	(Ves	O <sub>1</sub> o	OperatorNotified	Yes	Oyo	
Necessary Monthly Printout Taken	Yes Spill Buckets	O <sub>N</sub> o	OperatorNotified	Ores	O <sub>10</sub>	
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(XNo	OperatorNotified	(C)es	Ovo.	
Are the Spill Bucket in good condition and free of damage/cracks	Yes Fill Ports	Qvo	OperatorNotified	es es	8	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	No	OperatorNotified	Cres	Ovo	
P	iping/STP Sun	nps		0"		
Are Sumps Clean and free from water, debris, product etc?	Oyes	PNO	OperatorNotified	Ores	No	
Under Disp	enser Contain	ments (UDC)	)	7		
Are UDCs clean and free from water, debris, product etc?	Yes	(DNo	OperatorNotified	(V) Yes	ONO	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS FOLLOWING PROPER PR	POSSED OFF A	ACCORDING	TO EXISTING RULES	AND REQU	ULATIONS	
Operator on Duty Name		Signature		Date A	6-09-200	
317-645-0215 tank	sdata@gmail.c		Des		sdata.com	