

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

FEB 20. 2025 8:10 PM

CSLD TEST RESULTS

FEB 20. 2025 8:10 PM

T 1:REGULAR
PROBE SERIAL NUM 517863

0.2 GAL/HR TEST
PER: FEB 20. 2025 PASS

T 2:PREMIUM
PROBE SERIAL NUM 517864

0.2 GAL/HR TEST
PER: FEB 20. 2025 PASS

T 3:DIESEL
PROBE SERIAL NUM 636334

0.2 GAL/HR TEST
PER: FEB 20. 2025 PASS

T 4:KEROSENE
PROBE SERIAL NUM 212514

0.2 GAL/HR TEST
PER: FEB 20. 2025 PASS

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

FEB 20. 2025 8:10 PM

LIQUID STATUS

FEB 20. 2025 8:10 PM

L 1:NL SUMP
SENSOR NORMAL

L 2:PREM SUMP
SENSOR NORMAL

L 3:DIESEL SUMP
SENSOR NORMAL

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

FEB 20, 2025 8:10 PM

LEAK TEST REPORT

T 1:REGULAR
PROBE SERIAL NUM 517863

NO TEST DATA AVAILABLE

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

FEB 20, 2025 8:10 PM

LEAK TEST REPORT

T 2:PREMIUM
PROBE SERIAL NUM 517864

NO TEST DATA AVAILABLE

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

FEB 20, 2025 8:10 PM

LEAK TEST REPORT

T 3:DIESEL
PROBE SERIAL NUM 636334

NO TEST DATA AVAILABLE

SHELL
2535 HOYT
MUNCIE IN
765 284 2659

FEB 20, 2025 8:10 PM

LEAK TEST REPORT

T 4:KEROSENE
PROBE SERIAL NUM 212514

NO TEST DATA AVAILABLE