Tanks Data	30 DAYS WALK THROUGH INSPECTION
UST Facility I.D.((FID)# 7259	Contact Number
Facility Name Shelf	Contact email
Address 25355 Aroys ANG 47702	Date of Inspection 07-02-7025
Operator on Duty Name	Name of the Person Conducting Inspection Guzzbroet
O	perator Training /
Operator Training current	OYes ONo OperatorNotified OYes No
Is Registration current with correct owner, operator etc.	ation/Notification Form OYes No OperatorNotified Ores No
	Release Detection
Release Detection Method	GATG SIR OIC Other
Make and Model VR TLS - 33	SO. O. O. O. O. O.
Does it have paper?	OYes ONO OperatorNotified OYes
Is it in Alarm mode?	OYes ONO OperatorNotified Yes No
Interstitial Monitoring Sensor Status Normal	O'es O Operator Notified Yes
Necessary Monthly Printout Taken	OYes ONO OperatorNotified Oyes ONO
	Spill Buckets
Are Spill Buckets Clean and free from water, debris, product etc?	Ores One Operator Notified Ses
Are the Spill Bucket in good condition and free of damage/cracks	OYes ONO OperatorNotified Oes ONO
Is Fill pipe cap tight and fill pipe free from any obstruction?	Fill Ports  (Yes No Operator Notified (Yes Ovo
	oing/STP Sumps
Are Sumps Clean and free from water, debris, product etc?	Oyes Oyo OperatorNotified Oyes Oyo
Under Dispens	nser Containments (UDC)
Are UDCs clean and free from water, debris, product etc?	OYes ONO OperatorNotified OYes ONO
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOS	OSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS CEDUE BY A CERTIFIED CONTRACTOR.
Operator on Duty Name	Signature
마마트 : B.	ata@gmail.com
	20220516