Tanks Data	30 DAYS WALK THROUGH INSPECTION					
UST Facility I.D.((FID)# 7259	Contact Nu	Contact Number				
Facility Name Shell	Contact em	Contact email				
Address 2535 > Hogy AM94730) Date of Insp	Date of Inspection 08 - 09 - 7 028				
Operator on Duty Name		Name of the Person Conducting Inspection				
Operator Training //						
Operator Training current	Yes	ONo	OperatorNotified	Yes	No	
Registration/Notification Form						
Is Registration current with correct owner, operator etc.	Yes	(No	OperatorNotified	()Yes	Olo	
	Release Detection	on		0		
Release Detection Method	AIG	& LIM	OSIR	Oic	Other	
Make and Model VX TUS-5				_		
Does it have paper?	Yes	No.	OperatorNotified	Yes	Q40	
Is it in Alarm mode?	Yes	(2)No	OperatorNotified	Yes	QNo	
Interstitial Monitoring Sensor Status Normal	Yes	ON0	OperatorNotified	Yes	Oio	
Necessary Monthly Printout Taken	Yes	ONO	OperatorNotified	O'es	ONO	
Spill Buckets						
Are Spill Buckets Clean and free from water, debris, product etc'	><	ONO	OperatorNotified	es	Olo	
Are the Spill Bucket in good condition and free of damage/crack	s OYes	No	OperatorNotified	es	No	
	Fill Ports					
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	(No	OperatorNotified	Oes	Olo	
	Piping/STP Sun	ips				
Are Sumps Clean and free from water, debris, product etc?	Yes	Oyo	OperatorNotified	Ves	Olo	
Under Dispenser Containments (UDC)						
Are UDCs clean and free from water, debris, product etc?	Yes	90	OperatorNotified	Ores	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS FOLLOWING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR.						
Operator on Duty Name		Signature		Date		
317-645-0215 tanksdata@gmail.com www.tanksdata.com					lata.com	
					20220516	