Tanks Data	30 DAYS WALK THROUGH INSPECTION					
UST Facility I.D.((FID)# 7, 759	Contact No	Contact Number				
Facility Name SISS		Contact email				
Address 2 5355Hoy+ Rug 47307	The state of the s					
Operator on Duty Name						
		Name of the Person Conducting Inspection Gubboot				
0	perator Train					
Operator Training current	Oyes	ONo	OperatorNotified	Ores	Oio	
Registra	ation/Notificat	ion Form		~		
Is Registration current with correct owner, operator etc.	Yes	ONO	OperatorNotified	Ores	Oio	
# [5] '[1] [2] [4] [4] [4] [4] [4] [4] [4] [4] [4] [4	Release Detecti					
Release Detection Method	ATG	SIM	BIR	Oic	Other	
Make and Model UXTCS-3,	20			_		
Does it have paper?	Yes	QNo	OperatorNotified	Yes	Oto	
Is it in Alarm mode?	Yes	(A)No	OperatorNotified	Yes	Oio	
Interstitial Monitoring Sensor Status Normal	Q'es	Ovo	OperatorNotified	Ores	Oio	
Necessary Monthly Printout Taken	Yes	ONo	OperatorNotified	Ores	Oio	
	Spill Buckets				_	
Are Spill Buckets Clean and free from water, debris, product etc?	Ores	(QNo	OperatorNotified	Ocs	Oio	
Are the Spill Bucket in good condition and free of damage/cracks	@Yes	No	OperatorNotified	Cos	Olo	
	Fill Ports	\sim		_		
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	O _{No}	OperatorNotified	Oes	Oio	
	ping/STP Sun	nps				
Are Sumps Clean and free from water, debris, product etc?	Yes	(A)10	OperatorNotified	Cres	Olo	
	enser Contain	-				
Are UDCs clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified	Wes .	Oio	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO				AND REQUI	LATIONS	
Operator on Duty Name		Signature		Date		
317-645-0215 tanksdata@gmail.com				www.tanksdata.com		
					20220516	