Tanka Data	30 DAYS WALK THROUGH INSPECTION
ST Facility I.D.((FID)# 50120	Contact Number
acility Name A MOCO	Contact email
ddress 1338 W Samplest, Suth Bend,	Date of Inspection 11/10/29
perator on Duty Name	Name of the Person Conducting Inspection AKSNIT
Ope	erator Training
Operator Training current	Yes No OperatorNotified Yes No
Is Registration current with correct owner, operator etc.	don/Notification Form Yes No OperatorNotified Ces No
25일 등에 들어 있는데 불어 가장하는데 하는 물리를 가는데 하는데 하는데 하는데 하는데 되었다. 그런 물리를 가는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하는데 하	lease Detection
Release Detection Method	XATG CIM ORR OIC Other
Make and Model	VRTLS 350R
Does it have paper?	Kes No OperatorNotified Kes No
Is it in Alarm mode?	Yes No OperatorNotified Yes No
Interstitial Monitoring Sensor Status Normal	Yes No OperatorNotified Yes No
Necessary Monthly Printout Taken	Yes No OperatorNotified Ces No
	Spill Buckets
Are Spill Buckets Clean and free from water, debris, product etc?	Cles No OperatorNotified Ses No
Are the Spill Bucket in good condition and free of damage/cracks	Xes No OperatorNotified Cs No
Is Fill pipe cap tight and fill pipe free from any obstruction?	Ores No Operator Notified es No
P	iping/STP Sumps
Are Sumps Clean and free from water, debris, product etc?	Ores No OperatorNotified Cres No
Under Disp	enser Containments (UDC)
Are UDCs clean and free from water, debris, product eto?	Ores No OperatorNotified Ses No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS FOLLOWING PROPER PR	POSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS ROCEDUE BY A CERTIFIED CONTRACTOR.
Operator on Duty Name	Signature Date
	ksdata@gmail.com www.tanksdata.com