Tanks Data 30 DAYS WALK THROUGH INSPECTION						
UST Facility I.D.((FID) # <6176	Contact Number					
Facility Name AMOCO	Contact email					
Address 1 33 8 W Spyllo St 466 19	Date of Inspection 07-79-1015					
Operator on Duty Name	Name of the Person Conducting Inspection When the Person Conducting Inspection					
Op	erator Traini	ing		$\overline{}$	<u> </u>	
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONO	
Registrat	ion/Notificat	ion Form		0		
Is Registration current with correct owner, operator etc.	Yes	Oyo	OperatorNotified	Cres	O ₁₀	
Re	lease Detecti	on	<u> </u>	0	0	
Release Detection Method	MATG	CIM	SIR	Oic	Other	
Make and Model / RTL5-350,	e	_		_		
Does it have paper?	Yes	O _N o	OperatorNotified	Yes	Q10	
Is it in Alarm mode?	Yes	ON ₀	OperatorNotified	Yes	Qio	
Interstitial Monitoring Sensor Status Normal	Yes	ONO	OperatorNotified	Ores	O ₁₀	
Necessary Monthly Printout Taken	Yes	ONo	OperatorNotified	Ores	Ovo	
	Spill Buckets	s [
Are Spill Buckets Clean and free from water, debris, product etc?	Ores	9No	OperatorNotified	(G)es	Olo	
Are the Spill Bucket in good condition and free of damage/cracks	Yes Fill Ports	O _N o	OperatorNotified	Oes	O ₁₀	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	No	OperatorNotified	Oes	ONO	
[] 과 사용 회사 (1946년 - 1947년) 전 1947년 - 194	ping/STP Sur	mps		_	_	
Are Sumps Clean and free from water, debris, product etc?	Ores	(D)10	OperatorNotified	Pres	(No	
Under Dispe	enser Contair	nments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	(P)No	OperatorNotified	(C) Yes	ONO	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO				S AND REQ	ULATIONS	
Operator on Duty Name	Signature			Date	4-29-70	
317-645-0215 tanks	sdata@gmail.com			www.tank	www.tanksdata.com	