Tanks Data	30 DAYS WALK THROUGH INSPECTION
UST Facility I.D.((FID) # 0 16 274	Contact Number
Facility Name	Contact email
Address 17055R 135 8106	Date of Inspection 10-18-2025
Operator on Duty Name	Name of the Person Conducting Inspection Croppact
0	perator Training (No
Operator Training current	Oyes ONo OperatorNotified Oyes
Is Registration current with correct owner, operator etc.	Ation/Notification Form OYes Olo OperatorNotified Ores Olo
Release Detection Method	celease Detection OIC Other
Make and Model 5 - 750 1.  Does it have paper?	Oxes Oxo Operator Notified QYes Quo
Is it in Alarm mode?	Yes No Operator Notified Yes No
Interstitial Monitoring Sensor Status Normal	Yes No Operator Notified Yes No
Necessary Monthly Printout Taken	Yes No OperatorNotified Yes No Spill Buckets
Are Spill Buckets Clean and free from water, debris, product etc?	
Are the Spill Bucket in good condition and free of damage/cracks	
Is Fill pipe cap tight and fill pipe free from any obstruction?	O'es No Operator Notified Oes No Piping/STP Sumps
Are Sumps Clean and free from water, debris, product etc?	Ores Olo Operator Notified Ores Olo
The state of the s	penser Containments (UDC)
Are UDCs clean and free from water, debris, product etc?	Ores On Operator Notified Ores Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS FOLLOWING PROPER PR	ROCEDUE BY A CERTIFIED CONTRACTOR.
Operator on Duty Name	Signature
■ 기계는 그것이 없다면 보면서 이 병원에서 있다면 살아가고 있는데 일어 마시아이라고 하면 안에서 가면 하면 하는데	ksdata@gmail.com / Wyrle www.tanksdata.com