Tanks Data	3	30 DAYS V	VALK THROUGH	INSPEC	LION	
UST Facility I.D.((FID)# 1470/	Contact N	Contact Number				
Facility Name / TTG 6	Contact en	Contact email				
Address 12 47 0 0 100 5 # 46628	Date of Ins	Date of Inspection $8/-77-2075$				
Operator on Duty Name		Name of the Person Conducting Inspection Sucknown				
0	perator Train	ning		_		
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONo	
Registra	ation/Notifica	/ \		0		
Is Registration current with correct owner, operator etc.	Yes	. ONO	OperatorNotified	Ves	O40	
	elease Detecti		CIB	Orc	Other	
Release Detection Method	ATG	CIM	SIR	Oic	Ounci	
Make and Model UR 725	756		OnewaterNetified	Yes	\bigcap	
Does it have paper?	Yes	QN°	Operator Notified	\times	X	
Is it in Alarm mode?	Yes	QNo.	OperatorNotified	Yes	Χ.	
Interstitial Monitoring Sensor Status Normal	Yes	\bigcirc No	OperatorNotified	Yes	X,0	
Necessary Monthly Printout Taken	Yes	O _{No}	OperatorNotified	Yes	O _{No}	
	Spill Bucket	s				
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(O)10	OperatorNotified	es	QNo	
Are the Spill Bucket in good condition and free of damage/cracks	Yes	O _{No}	OperatorNotified	Oes	Oyo	
	Fill Ports	~		^		
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	O _{No}	OperatorNotified	Oes	Olo	
	ping/STP Sur	0		0	<u> </u>	
Are Sumps Clean and free from water, debris, product etc?	Yes	Ø ₁ o	OperatorNotified	Yes	ONO	
	enser Contain					
Are UDCs clean and free from water, debris, product etc?	Yes	(No	OperatorNotified	_	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF OCEDUE BY A	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQUL	ATIONS	
Operator on Duty Name		Signature		Date 00	7-70	
F	data@gmail.c	om /		www.tanksda	ata.com	
					20220516	