	30 DAYS WALK THROUGH INSPECTION
UST Facility I.D.((FID)# 14796	Contact Number
Facility Name (1700)	Contact email
Address 47 1/04/10 (446623	Date of Inspection 09-75-00
Operator on Duty Name	Name of the Person Conducting Inspection  Guarda 2001
Operator Training	
Operator Training current	Yes No OperatorNotified Yes No
Registratio	on/Notification Form
Is Registration current with correct owner, operator etc.	Yes No OperatorNotified Yes No
Rele	ase Detection
Release Detection Method	ATG CIM OSIR OIC Other
Make and Model VS-	37 /
Does it have paper?	Yes No OperatorNotified Yes No
Is it in Alarm mode?	Yes No OperatorNotified Yes No
Interstitial Monitoring Sensor Status Normal	Yes No OperatorNotified Yes No
Necessary Monthly Printout Taken	Yes No OperatorNotified Yes No
Spill Buckets	
Are Spill Buckets Clean and free from water, debris, product etc?	Yes No Operator Notified Yes No
Are the Spill Bucket in good condition and free of damage/cracks	Yes No Operator Notified Ses No
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes No Operator Notified Yes No
Piping/STP Sumps	
Are Sumps Clean and free from water, debris, product etc?	Yes No OperatorNotified Yes No
Under Dispenser Containments (UDC)	
Are UDCs clean and free from water, debris, product etc?	Yes Operator Notified Oes Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS FOLLOWING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR.	
Operator on Duty Name	Signature
317-645-0215 tanksdata@g	gmail.com www.tanksdata.com 20220516