Tanks Data	3	30 DAYS W	ALK THROUGH	I INSPE	CTION
UST Facility I.D.((FID)# 12246	Contact Number				
Facility Name Malif	Contact email				
Address 601 N Marin Street 46 545	Date of Inspection 06-12-2025				
Operator on Duty Name	Name of the Person Conducting Inspection Graphreet				
Op	perator Train	ning			
Operator Training current	Yes	ON <sub>o</sub>	OperatorNotified	Yes	ONo
	tion/Notificat	tion Form		$\overline{}$	
Is Registration current with correct owner, operator etc.	Yes	. ONO	OperatorNotified	Ves	O <sub>1</sub> o
	elease Detecti	_	<u></u>	O	<u> </u>
Release Detection Method	ATG	CIM	OSIR	Oic	Other
Make and Model $VR/25-35$	6	_			
Does it have paper?	Yes	QN <sub>0</sub>	OperatorNotified	Yes	$\bigcirc$
Is it in Alarm mode?	Yes	ON <sub>0</sub>	OperatorNotified	Yes	$\bigcirc$ Vo
Interstitial Monitoring Sensor Status Normal	Yes	(V)	OperatorNotified	Ores	Ovo
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	O'es	ONO
	Spill Buckets	s			
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	No	OperatorNotified	es	Olo
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	No
	Fill Ports				
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	ONO	OperatorNotified	Oes	No
Pip	ing/STP Sun	nps		_	
Are Sumps Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	Yes	No
Under Disper	iser Contain	ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	(V)No	OperatorNotified	(V) Yes	No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PROC				AND REQUI	LATIONS
perator on Duty Name		Signature		Date 6	6-12-202
	ata@gmail.co	2	rees	www.tanksd	하다 마이트 이번 내가 되었다. 이번 이번 사람들이 되었다.