

429 N MAIN ST  
ELKHART, IN 46516

OCT 28, 2024 16:41

CSLD TEST RESULTS

OCT 28, 2024 16:41

T 1:RUL  
PROBE SERIAL NUM 444915

0.2 GAL/HR TEST  
PER: OCT 28, 2024 PASS

T 2:PREMIUM  
PROBE SERIAL NUM 710749

0.2 GAL/HR TEST  
PER: OCT 28, 2024 PASS

\*\*\*\*\* END \*\*\*\*\*

429 N MAIN ST  
ELKHART, IN 46516

OCT 28, 2024 16:41

LIQUID STATUS

OCT 28, 2024 16:41

L 1:RUL INTERSTITIAL  
SENSOR NORMAL

L 2:RUL SUMP  
SENSOR NORMAL

L 3:PREM SUMP  
SENSOR NORMAL

\*\*\*\*\* END \*\*\*\*\*

429 N MAIN ST  
ELKHART, IN 46516

OCT 28, 2024 16:41

LEAK TEST REPORT

T 1:RUL  
PROBE SERIAL NUM 444915

NO TEST DATA AVAILABLE

\*\*\*\*\* END \*\*\*\*\*

429 N MAIN ST  
ELKHART, IN 46516

OCT 28, 2024 16:41

LEAK TEST REPORT

T 2:PREMIUM  
PROBE SERIAL NUM 710749

NO TEST DATA AVAILABLE

\*\*\*\*\* END \*\*\*\*\*