

30 DAYS WALK THROUGH INSPECTION

000
Tanks Data

UST Facility I.D. (EID) #	9066	Contact Number	
Facility Name	MOBILE	Contact email	
Address	429 N Mainst, SIKHART, IN	Date of Inspection	10/28/24
Operator on Duty Name	46516	Name of the Person Conducting Inspection	AKSHIT

Operator Training

Is Registration current with correct owner, operator etc.

Registration/Notification Form
☒ Yes
☐ No

Operator Notified
☐ Yes
☐ No

Release Detection Method

Make and Model

Release Detection
☒ ATG
☐ DIM
☐ SIR
☐ IC
☐ Other

Does it have paper?

Is it in Alarm mode?

Interstitial Monitoring Sensor Status Normal
 Necessary Monthly Printout Taken

Spill Buckets

Are Spill Buckets Clean and free from water, debris, product etc?
 Are the Spill Bucket in good condition and free of damage/cracks

☒ Yes
☐ No

Operator Notified
☒ Yes
☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

☒ Yes
☐ No

Operator Notified
☐ Yes
☐ No

Are Sumps Clean and free from water, debris, product etc?

☒ Yes
☐ No

Operator Notified
☐ Yes
☐ No

Are UDCs clean and free from water, debris, product etc?

☐ Yes
☒ No

Operator Notified
☒ Yes
☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

317-645-0215

tanksdata@gmail.com

Signature

Date

www.tanksdata.com