

30 DAYS WALK THROUGH INSPECTION

Tanks Data

UST Facility I.D. (FID) #	9066	Contact Number	
Facility Name	Mobil	Contact email	
Address	429 Walnut, Sikeston,	Date of Inspection	02/27/25
Operator on Duty Name	ALYSSA	Name of the Person Conducting Inspection	ALYSSA

Operator Training current ☐ Yes ☐ No ☐ Operator Notified ☐ Yes ☐ No

Registration current with correct owner, operator etc. ☐ Yes ☐ No ☐ Operator Notified ☐ Yes ☐ No

Release Detection Method ☐ PATG ☐ CIM ☐ BIR ☐ IC ☐ Other

Make and Model

Does it have paper?

Is it in Alarm mode?

Interstitial Monitoring Sensor Status Normal
Necessary Monthly Printout Taken

Spill Buckets

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Are Spill Buckets Clean and free from water, debris, product etc?

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Fill Ports

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Piping/STP Sumps

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Are Sumps Clean and free from water, debris, product etc?

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Under Dispenser Containments (UDC)

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Are UDCs clean and free from water, debris, product etc?

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com