

5296 Breakers Way, Carmel, IN 46033

Date 10/20/25

LIQUID SENSOR FUNCTIONALITY TESTING

Facility Name:	Mobil
Address:	429 N Main St
City, State, Zip Code:	Elkhart, IN 46516
Facility I.D. #:	9066

Owner:	VIP CRE Investments LLC
Address:	7054 Kennesaw Dr
City, State, Zip Code:	Brownsburg, IN, 46112
Phone #:	

This procedure is to determine whether liquid sensors located in the interstitial space of UST systems are able to detect the presence of water and fuel. See PEI/RP1200 Section 8.3 for the test procedure.

Sensor Location	IM 1	STP 1	STP 2				
Product Stored	Regular	Regular	Premium				
Type of Sensor	Non-Discr ☐	Non-Discr ☐	Non-Discr ☐	☐	☐	☐	☐
Test Liquid	Water ☐	Water ☐	Water ☐	☐	☐	☐	☐
Is the ATG console clear of any active or recurring warnings or alarms regarding the leak sensor? If the sensor is in alarm and functioning, indicate why.	Yes ☐	Yes ☐	Yes ☐	☐	☐	☐	☐
Is the sensor alarm circuit operational?	Yes ☐	Yes ☐	Yes ☐	☐	☐	☐	☐
Has sensor been inspected and in good operating condition?	Yes ☐	Yes ☐	Yes ☐	☐	☐	☐	☐
When placed in the test liquid, does the sensor trigger an alarm?	Yes ☐	Yes ☐	Yes ☐	☐	☐	☐	☐
When an alarm is triggered, is the sensor properly identified on the ATG console?	Yes ☐	Yes ☐	Yes ☐	☐	☐	☐	☐
Any "No" answers indicates the sensor fails the test.							
Test Results	Pass ☐	Pass ☐	Pass ☐	☐	☐	☐	☐

ATG shows both STP sensors are tripped but when you print out alarm report, it shows "All Functions Normal" When removed and tripped, it did show on the print out.

Comment

Tester's Name : Josh Rider

Tester's Signature : 