NO PRINTER!

IST Facility I.D.((FID)# 16559  acility Name SUNCO  address 20 N Chestbut St, Mob Muia, perator on Duty Name  1N 46157  Ope	計算ないのう	30 DAYS WALK THROUGH INSPECTION lumber mail spection 09/26/29 he Person AKSn/7 ming	I INSPEC	CTION	
Operator Training current  Registration current with correct owner, operator etc.	Operator Training  Oyes  No  Registration/Notification Horm	OperatorNotified		Ş Ş	
Is Registration current with correct owner, operator etc.  Release Detection Method	Oyes Oto Release Detection Oyarg Orim	OperatorNotified	Š Š		-
	AR	OSITESENTIAL.	Ç		-
Does it have paper?		OperatorNotified	Q	Ô	-
Is it in Alarm mode?		OperatorNotified	$\bigotimes_{i_0}$	Ô	-
Interstitial Monitoring Sensor Status Normal Necessary Monthly Printout Taken	Ö Ö Ö	OperatorNotified OperatorNotified	Ö	ÔÔ	
Are Spill Buckets Clean and free from water, debris, product etc?  Are the Spill Bucket in good condition and free of damage/cracks		OperatorNotified OperatorNotified	ÕÕ	ÖÖ	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Phoine/STP Summs	OperatorNotified	Q	Q	
Are Sumps Clean and free from water, debris, product etc?  Under Dispen	ut etc? Oxes Olo Under Dispenser Containments (UDC)	OperatorNotified	Q	Ô	
Are UDCs clean and free from water, debris, product etc?	Okes No SSED OFF ACCORDING EDUE BY A CERTIFIED	OperatorNotified FIO EXISTING RULES A CONTRACTOR.	⊘es AND REQUI.	OIO	
perator on Duty Name	Signature		Date		
317-645-0215 tanksda	tanksdata@gmail.com		www.tanksdata.com		
				30220516	