

30 DAYS WALK THROUGH INSPECTION

_____ 0000 ____
Tanks Data

UST Facility I.D. (FID) # 16559

Contact Number

Facility Name SUNOCO

Contact email

Address 20 N Chestnut St, Monrovia, IN 46157

Date of Inspection 10/22/24

Operator on Duty Name

IN 46157

Name of the Person Conducting Inspection AK SMIT

Operator Training current

Operator Training
☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Is Registration current with correct owner, operator etc.

Registration/Notification Form
☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Release Detection Method

Release Detection
☒ ATG ☐ STM

SIR

☐ OC ☐ Other

Make and Model

MANVO

Does it have paper?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Is it in Alarm mode?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Interstitial Monitoring Sensor Status Normal

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Necessary Monthly Printout Taken

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Spill Buckets

☐ Yes ☒ No

Operator Notified

☒ Yes ☐ No

Are Spill Buckets Clean and free from water, debris, product etc?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Are the Spill Bucket in good condition and free of damage/cracks

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

Fill Ports
☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Are Sumps Clean and free from water, debris, product etc?

Pipeline/STP Sumps
☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Under Dispenser Contaminants (UDC)

☐ Yes ☒ No

Operator Notified

☒ Yes ☐ No

Are UDCs clean and free from water, debris, product etc?

☐ Yes ☒ No

Operator Notified

☒ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tankdata@gmail.com

www.tankdata.com

20220516

NO
PRINTER