NOATG

1 V V V I I V V	THE OLICH INSPECTION
	30 DAYS WALK THROUGH INSPECTION
Taraka Data	
JST Facility I.D.((FID) # 16559	Contact Number
Facility Name (NCV ()	Contact email
Address ZON Chartnet Sty 6182	Date of Inspection 87-14-70/5
Operator on Duty Name	Name of the Person Conducting Inspection Guybreet
Operator Training current	Operator Training Oyes ONo OperatorNotified Oyes ONo
Is Registration current with correct owner, operator etc.	ration/Notification Form OYes Oo OperatorNotified Ores Oo
Release Detection Method	Release Detection OIC Other
Make and Model	
Does it have paper?	OYcs ONo OperatorNotified OYes
Is it in Alarm mode?	Yes No OperatorNotified Yes No
Interstitial Monitoring Sensor Status Normal	Yes No OperatorNotified Yes No
Necessary Monthly Printout Taken	Yes No OperatorNotified Yes No
	Spill Buckets
Are Spill Buckets Clean and free from water, debris, product of	etc? O'res OperatorNotified O'es No
Are the Spill Bucket in good condition and free of damage/cra	
Is Fill pipe cap tight and fill pipe free from any obstruction	
Are Sumps Clean and free from water, debris, product etc?	Piping/STP Sumps OYes Olo OperatorNotified Ores Olo
Are UDCs clean and free from water, debris, product etc	Dispenser Containments (UDC) Yes Operator Notified Oyes No
FOLLOWING PROPE	C DISPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS OR PROCEDUE BY A CERTIFIED CONTRACTOR.
Operator on Duty Name	
317-645-0215	tanksdata@gmail.com Date Date Z Y Z Z Z Z Z Z Z Z

20220516