Tanks Data	30	DAYS W	ALK THROUGH	INSPEC	TION
UST Facility I.D.((FID) # 3 403	Contact Number				
Facility Name / aléria	Contact email				
Address 60 3 / 10/08/14/24 46178	Date of Inspection $60-76-76$				
Operator on Duty Name	Name of the Person Conducting Inspection  Out 201  Conducting Inspection				
Op	erator Training				
Operator Training current	Yes	ON <sub>0</sub>	OperatorNotified	Yes	(No
Is Registration current with correct owner, operator etc.	ion/Notification	No	OperatorNotified	Ores	Oio
	lease Detection			0.0	
Release Detection Method  Make and Model ( / S	ATG	CIM	OSIR	Oic	Other
Does it have paper?	Wes	No	OperatorNotified	Yes	Oio
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	ONO
Necessary Monthly Printout Taken	Yes	ON0	OperatorNotified	Ores	Olo
	Spill Buckets			$\sim$	
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	ONO .	OperatorNotified	es	QVo.
Are the Spill Bucket in good condition and free of damage/cracks	Fill Ports	ONO	OperatorNotified	Oes	Oyo
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	Ovo	OperatorNotified	Oes	Oio
The state of the s	ping/STP Sum	ps			
Are Sumps Clean and free from water, debris, product etc?	Yes	Oyo	OperatorNotified	Vres	Oyo
The state of the s	enser Containr				
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	-	No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISE FOLLOWING PROPER PRO	POSSED OFF A OCEDUE BY A	CCORDING	TO EXISTING RULE.  CONTRACTOR.	S AND REQ	ULATIONS
Operator on Duty Name		Signatur		Date	
	317-645-0215 tanksdata@gmail.com			www.tanksdata.com	