

Petroleum Testing Services

PO BOX 146
Yorktown, IN 47396
(765) 749-5540

Email: petroleumtesting@aol.com

DATE:2-25-2022	TIME: 1:00p
SITE ADDRESS	
Marathon	
4 W Main St	
Chesterfield, IN 46017	

SPILL BUCKET INTEGRITY TEST

TANK	1	2	3	4	
PRODUCT	UNL	PREM	DSL	REC90	
SPILL BUCKET CAPACITY	5	5	5	5	
SINGLE/DOUBLE WALLED	S	S	S	S	
LIQUID/DEBRIS REMOVED	Y	Y	Y	Y	
VISUAL INSPECTION	OK	OK	OK	OK	
TANK RISER CAP INCLUDED?	Y	Y	Y	Y	
DRAIN VALVE INCLUDED?	Y	Y	Y	Y	
STARTING LEVEL	12	13	13	12	
TYPE OF TEST	H	H	H	H	
ENDING LEVEL	12	13	13	12	
TEST DURATION	1HR	1HR	1HR	1HR	
LEVEL CHANGE	0	0	0	0	
RESULT	PASS	PASS	PASS	PASS	

OVERFILL INSPECTION

TANK #	1	2	3		
PRODUCT	UNL	PREM	DSL	REC90	
TANK DIAMETER	91	91	91	71	
TANK VOLUME	8000	8000	6000	2000	
TYPE OF OVERFILL	AUTO	AUTO	AUTO	BF	
OVERFILL MECHANISM IS FREE FROM DEBRIS	Y	Y	Y		
OVERFILL MECHANISM MOVES FREELY	Y	Y	Y		
TOP OF RISER TO TANK BOTTOM	135	130	127		
TOP OF RISER TO OVERFILL	50	45	42		
HT OF OVERFILL FROM TANK BOTTOM	85	85	85		
OVERFILL IS ADJUSTED TO 95% OF TANKS CAPACITY	Y	Y	Y		
RESULT	PASS	PASS	PASS	*	

*Could not remove vapor adapter from tank. Ball float could not be verified or tested.

INSPECTED BY: RONNIE BROWN

UC2017IN12086