	3	0 DAYS W	ALK THROUGH	INSPEC	CTION	
Tanks Data						
UST Facility I.D.((FID) # 14973	Contact Number					
Facility Name Morathon	Contact em	Contact email				
Address you May 5+ 46017	Date of Inspection 06-25-2025					
Operator on Duty Name	Name of the Person Conducting Inspection Swyl rest					
Op	erator Train	ing		0.	O.	
Operator Training current	Yes	ON ₀	OperatorNotified	Yes	ON0	
	tion/Notificat		ONetfied	Ores	Ora	
Is Registration current with correct owner, operator etc.	Yes elease Detection	on No	OperatorNotified	Cres	Ovo	
Release Detection Method	CATG	C TIM	OSIR	OIC	Other	
Make and Model OPW TANKSEN	TINENT	ALNAN	6			
Does it have paper?	Yes	ON ₀	OperatorNotified	Yes	Oto	
Is it in Alarm mode?	Yes	ON ₀	OperatorNotified	Ores	Olo	
Interstitial Monitoring Sensor Status Normal	(4) Yes	Ovo	OperatorNotified	Ores	O40	
Necessary Monthly Printout Taken	Yes	O _N o	OperatorNotified	Ores	Ovo	
	Spill Buckets	, _				
Are Spill Buckets Clean and free from water, debris, product etc?	O'res	ØN₀	OperatorNotified	(G)es	Olo	
Are the Spill Bucket in good condition and free of damage/cracks	(O)Yes	O _N o	OperatorNotified	Oes	O ₁₀	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Fill Ports Yes	ONO	OperatorNotified	Oes	(No	
. (사) 경기 있는 사람들은 다른 하다구나는 가는 사람들은 얼마 되면 보고 있는데 되면 되었다. 그는 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은	ping/STP Sun	nps				
Are Sumps Clean and free from water, debris, product etc?	Yes	(No	OperatorNotified	Ores	(No	
Under Dispe	nser Contain	ments (UDC))			
Are UDCs clean and free from water, debris, product etc?	Yes	(No	OperatorNotified	Pres	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO	$CEDUE\ BY\ A$	CFRTIFIFD	CONTRACTOR	AND REQU	ULATIONS	
Operator on Duty Name	Signature			Date 06-25-2025 www.tanksdata.com		
317-645-0215 tankso	Signature lata@gmail.com					
		0-1			20220516	