

Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) # 10361

Contact Number

Facility Name Mayahm

Contact email

Address 2754 E 100 S Anderson, IN 46017

Date of Inspection 11/26/2024

Operator on Duty Name Melick

Name of the Person Conducting Inspection W. Emerson

Operator Training current

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Registration/Notification Form

Is Registration current with correct owner, operator etc.

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Release Detection

Release Detection Method

☒ ATG

☐ CIM

☐ SIR

☐ IC

☐ Other

Make and Model VR TS 350

Does it have paper?

☒ Yes

☐ No

Operator Notified

☐ Yes ☐ No

Is it in Alarm mode?

☐ Yes

☒ No

Operator Notified

☐ Yes ☐ No

Interstitial Monitoring Sensor Status Normal

☐ Yes

☒ No

Operator Notified

☐ Yes ☐ No

Necessary Monthly Printout Taken

☒ Yes

☐ No

Operator Notified

☐ Yes ☐ No

Spill Buckets

Are Spill Buckets Clean and free from water, debris, product etc?

☐ Yes

☒ No

Operator Notified

☐ Yes ☐ No

Are the Spill Bucket in good condition and free of damage/cracks

☐ Yes

☒ No

Operator Notified

☐ Yes ☐ No

Fill Ports

Is Fill pipe cap tight and fill pipe free from any obstruction?

☒ Yes

☐ No

Operator Notified

☐ Yes ☐ No

Piping/STP Sumps

Are Sumps Clean and free from water, debris, product etc?

☐ Yes

☒ No

Operator Notified

☐ Yes ☐ No

Under Dispenser Containments (UDC)

Are UDCs clean and free from water, debris, product etc?

☐ Yes

☒ No

Operator Notified

☐ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com