

Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) #		10361	
Facility Name	Merkon		
Address	2754 E 100 S, Anderson, UT		
Operator on Duty Name	JN-46017		
Contact Number		05-05-25	
Contact email		Merkon.Singh	
Date of Inspection		05-05-25	
Name of the Person Conducting Inspection		Merkon Singh	

Operator Training current	☒ Yes	☐ No	Operator Training	☐ Yes	☐ No
Is Registration current with correct owner, operator etc.	☐ Yes	☐ No	Registration/Notification Form	☐ Yes	☐ No
Release Detection Method	☒ ATG	☐ CIM	Release Detection	☐ Yes	☐ No
Make and Model	V8-TLS300				
Does it have paper?	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Is it in Alarm mode?	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Interstitial Monitoring Sensor Status Normal	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Necessary Monthly Printout Taken	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Are Spill Buckets Clean and free from water, debris, product etc?	☒ Yes	☐ No	Spill Buckets	☐ Yes	☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes	☐ No	Fill Ports	☐ Yes	☐ No
Are Sumps Clean and free from water, debris, product etc?	☒ Yes	☐ No	Piping/STP Sumps	☐ Yes	☐ No
Are UDCs clean and free from water, debris, product etc?	☒ Yes	☐ No	Under Dispenser Containments (UDC)	☐ Yes	☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name: _____ Signature: _____ Date: _____

317-645-0215 tanksdata@gmail.com www.tanksdata.com 2020516