2 mark

Tanks Data	30 DAYS	WALK THROUGH	HINSPE	CTION
UST Facility I.D.((FID) # 10361	Contact Number			
Facility Name My My Long	Contact email			
Address 2754 E1005 96017	Date of Inspection 07-02-7025			
Operator on Duty Name	Name of the Person Conducting Inspection Greenbroot			
	Operator Training	/	0	Ova
Operator Training current	OYes ONo	OperatorNotified	Yes	ONO
Is Registration current with correct owner, operator etc.	Yes No	OperatorNotified	Ores	Oto
Release Detection Method	Release Detection	SIR	OIC	Other
Make and Model URTLS— Does it have paper?	Ores QNo	OperatorNotified		Qio
Is it in Alarm mode?	Oves ONo	OperatorNotified		X
Interstitial Monitoring Sensor Status Normal	Oes ONo	OperatorNotified		X10
Necessary Monthly Printout Taken	Yes ONo	OperatorNotified	Yes	ON0
	Spill Buckets		0	
Are Spill Buckets Clean and free from water, debris, product etc	? Ores To	OperatorNotified	Ses	N°
Are the Spill Bucket in good condition and free of damage/crack	s Pes ONo	OperatorNotified	Oes	ONO.
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes No	OperatorNotified	Oes	Olo
Is I'm pipe cap tight and i'm pipe itee	Piping/STP Sumps		6	O:
Are Sumps Clean and free from water, debris, product etc?	OYes ONO	OperatorNotified	Ves	Oxo
Under Dis	penser Containments (UD	C)	0	
Are UDCs clean and free from water, debris, product etc?	OYes ONo	OperatorNotified	Ses .	TATIONS
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS	SPOSSED OFF ACCORDIN ROCEDUE BY A CERTIFIE	G TO EXISTING RULES. D CONTRACTOR.	AND REQU	2-02-Z02
Operator on Duty Name	Signatur	re		
317-645-0215 tank	ksdata@gmail.com	of the same of the	www.tanksd	ata.com 20220516