Tanks Data	30 DAYS WALK THROUGH INSPECTION
UST Facility I.D.((FID) # 10 361	Contact Number
Facility Name Newhort-	Contact email
Address 2 759 F1005 46617	Date of Inspection $06-09-2025$
Operator on Duty Name	Name of the Person Conducting Inspection Creekeal
Op	perator Training
Operator Training current	Oyes Ono OperatorNotified Oyes ONo
Is Registration current with correct owner, operator etc.	Yes Ovo Operator Notified Ores Ovo
Release Detection Method	elease Detection OIC Other
Make and Model 1/R T/G-	366
Does it have paper?	Oyes No OperatorNotified Oyes Ovo
Is it in Alarm mode?	Yes No OperatorNotified Yes No
Interstitial Monitoring Sensor Status Normal	Yes No OperatorNotified Ores No
Necessary Monthly Printout Taken	Yes No OperatorNotified Oes No
	Spill Buckets
Are Spill Buckets Clean and free from water, debris, product etc?	
Are the Spill Bucket in good condition and free of damage/cracks	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Fill Ports  Yes No Operator Notified ()es No
[2] [4] [4] [4] [4] [4] [4] [4] [4] [4] [4	Piping/STP Sumps
Are Sumps Clean and free from water, debris, product etc?	Oyes Olo OperatorNotified Oyes Olo
Under Dis	spenser Containments (UDC)
Are UDCs clean and free from water, debris, product etc?	OYes OperatorNotified Oyes Oo
NOTE: ALL LIQUID/DEBRIS OR WAST'E MUST BE DISPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS FOLLOWING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR.	
Operator on Duty Name	Signature Date $0/-39-25$
317-645-0215 tar	nksdata@gmail.com www.tanksdata.com

A second of the second of the