

30 DAYS WALK THROUGH INSPECTION

Tanks Data

UST Facility I.D. (FID) #	50134	Contact Number	
Facility Name	McArthur	Contact email	
Address	1110 Northville Rd, Bristol	Date of Inspection	05-25-25
Operator on Duty Name	JN 246507	Name of the Person Conducting Inspection	Robert Singh

Operator Training current

Operator Training

Operator Notified

☐ Yes ☐ No

☐ No

Is Registration current with correct owner, operator etc.

Registration/Notification Form

Operator Notified

☐ Yes ☐ No

☐ No

Release Detection Method

Release Detection

Operator Notified

☐ Yes ☐ No

☐ Other

Make and Model

ATG
JR-TLS 450 Plus

Does it have paper?

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ No

Is it in Alarm mode?

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ No

Interstitial Monitoring Sensor Status Normal

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ No

Necessary Monthly Printout Taken

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ No

Spill Buckets

Are Spill Buckets Clean and free from water, debris, product etc?

☐ Yes ☒ No

Operator Notified

☐ Yes ☐ No

☐ No

Are the Spill Bucket in good condition and free of damage/cracks

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ No

Fill Ports

Is Fill pipe cap tight and fill pipe free from any obstruction?

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ No

Piping/STP Sumps

Are Sumps Clean and free from water, debris, product etc?

☐ Yes ☒ No

Operator Notified

☐ Yes ☐ No

☐ No

Under Dispenser Containments (UDC)

Are UDCs clean and free from water, debris, product etc?

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com