Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # 50194	Contact Number				
Facility Name AWS	Contact email				
Address 1 (10 Matti i 000 Rd 46507	Date of Inspection 66 - 76 - 2025				
Operator on Duty Name	Name of the Person Conducting Inspection Gurkeet				
Op	erator Trai				
Operator Training current	Yes	ONo	OperatorNotified	Yes	(No
Registration/Notification Form					
[[[[[[[[[[[[[[[[[[[[[[[[[[[[[[[[[[[[[[Yes		OperatorNotified	O'res	Oio
	lease Detec	tion		_	
Release Detection Method	ATG	CIM	SIR	OIC	Other
Make and Model 15-45	Jeff.			_	
Does it have paper?	Yes	O _{No}	OperatorNotified	Yes	Oto
Is it in Alarm mode?	Yes	ON ₀	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	ONO	OperatorNotified	Yes	Olo
Necessary Monthly Printout Taken	Yes	ONO	OperatorNotified	Yes	No
	Spill Buck	ets		~	
Are Spill Buckets Clean and free from water, debris, product etc?	Ores	ONO	OperatorNotified	Ces	(No
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	No
	Fill Ports	s			
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	Ovo	OperatorNotified	O es	Olo
Piping/STP Sumps					
Are Sumps Clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified	(Ozes	Olo
THE PROPERTY OF THE PROPERTY O		inments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	(C)No	OperatorNotified	Ø res	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OF A	F ACCORDING T A CERTIFIED C	O EXISTING RULES ONTRACTOR.	AND REQUI	LATIONS
Operator on Duty Name		Signature		Date /	(-76-2025
317-645-0215 tanks	tanksdata@gmail.com			www.tanksdata.com	
		0-1			20220516