Tanks Data	3	0 DAYS W	ALK THROUGH	INSPEC	TION	
UST Facility I.D.((FID) # 1/50 9	Contact Nu	Contact Number				
Facility Name (ITG)	Contact em	Contact email				
Address 9 900 Baroduces -	Date of Ins	Date of Inspection 77-06-202				
Operator on Duty Name		Name of the Person Conducting Inspection  Court rest				
Op	perator Train					
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONo	
	tion/Notificat			0	O.	
Is Registration current with correct owner, operator etc.	Yes	ON0	OperatorNotified	Ves	Oyo	
Release Detection Method	ATG	(TIM	OBIR.	OIC	Other	
Make and Model (/ 4 T) (-3	Sand	Upin	Onn	O.		
Does it have paper?	Yes	No	OperatorNotified	Yes	Oto	
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	Ovo	
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	O <sub>10</sub>	
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Yes	No	
생활 경영합니다. 양생 여자보다 아들은 아니다. 아니 하나 아니는 아니라 아니라 아들은 아들이 아내려가 나를 하는데 아름다는 아름다면 하다니다. 아름다는 아름다는 아름다는 아름다는 아름다는 아름다는 사람이 아름다는 아름다는 아름다는 아름다는 아름다는 아름다는 아름다는 아름다는	Spill Buckets					
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	ONo	OperatorNotified	(P)es	Oio	
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	No	
Are the Spill Bucket in good condition and free of damage/enders	Fill Ports	0				
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	No	OperatorNotified	Oes	Oio	
	oing/STP Sun	nps		~		
Are Sumps Clean and free from water, debris, product etc?	Yes	(F)Vo	OperatorNotified	@res	O <sub>10</sub>	
Under Disper	nser Contain	ments (UDC)				
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified		Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO	OSSED OFF A	ACCORDING CERTIFIED	TO EXISTING RULES CONTRACTOR.			
erator on Duty Name		Signature		Date()	7-06-2	
317-645-0215 tanksdata@gmail.com				www.tank	sdata.com	
317-045-0215					2022051	